



POOR COVERAGE

CAUSES:

- incorrect application technique
- inadequate mixing of materials
- excessive dilution

PREVENTION:

- apply the paint correctly, making sure that the layer obtained is uniform
- mix the substances thoroughly
- increase paint viscosity

RESTORATION:

- remove coating, clean the substrate and repaint it