



SLOW DRYING

CAUSES:

- application of a too thick layer of paint
- adverse weather conditions: cold, humidity, poor air circulation
- incorrect drying time
- use of not recommended or bad quality thinners

PREVENTION:

- apply the correct amount of paint
- ensure adequate warm and ventilated air circulation, avoiding cold and very humid environments
- use recommended thinners

RESTORATION:

- remove coating, clean the substrate and repaint it