



## DRY SPRAY

---

### CAUSES:

---

- incorrect application technique
- high air humidity and/or wet surface
- incorrect drying and/or curing times
- use of not appropriate thinner
- incorrect coating thickness applied

### PREVENTION:

---

- adopt application techniques as indicated in the technical data sheet
- use recommended thinners

### RESTORATION:

---

- remove coating, clean the substrate and repaint it