



## HAZE

### CAUSES:

- adverse weather conditions
- use of unsuitable thinners
- inadequate air pressure
- forced drying, more than allowed

### PREVENZIONE:

- avoid paint application in adverse climatic conditions (humidity, cold)
- use recommended thinners
- make sure the spray booth is adequately climate controlled

### RESTORATION:

- remove coating, clean the substrate and repaint it