



## POOR NON-STICK PERFORMANCE

---

### CAUSES:

---

- incorrect flash-off/curing temperatures
- not sufficient amount of topcoat applied
- inadequate product mixing
- excessive dilution

### PREVENTION:

---

- follow the application instructions in the technical data sheet

### RESTORATION:

---

- remove coating, clean the substrate and repaint it