



STAINS

CAUSES:

- incorrect application technique, drying times and temperatures
- incorrect spray gun pressure
- use of unsuitable thinners

PREVENTION:

- use application techniques and material preparation as stated in the technical data sheet
- check the spray gun pressure, keeping it parallel to the substrate to be painted
- grant adequate drying times
- use recommended thinners

RESTORATION:

- Remove coating, clean the substrate and repaint it